UNITED STATES DISTRICT COURT DISTRICT OF MASSACHUSETTS

VERMONT MUTUAL INSURANCE COMPANY, a/s/o ROBERT and NANCY MCNEIL, and ROBERT and NANCY MCNEIL,

Plaintiffs,

V.

C.A. No. 04CV12257NG

HAMILTON BEACH PROCTOR-SILEX, INC., Defendant.

DEFENDANT'S MOTION IN LIMINE REGARDING SUBSEQUENT UL LISTINGS

Now comes the Defendant and moves for an Order precluding reference by the plaintiff's engineering expert, Michael J. Rains, to the revised Underwriters' Laboratory ("UL") listing which was adopted after the date of manufacture of the subject toaster, and to the role of the CPSC in the implementation of the revision.

The Defendant refers the Court to Section 2 of Rains' so-called "Comments of Report of John J. Datovech" which was incorporated by reference as the Plaintiffs' Supplemental Disclosure (Exhibit A). (It should be noted that Defendant has filed a Motion to Strike the entire Supplemental Expert Disclosure on the grounds it was not made in a timely manner.)

In Section 2 – "Data Collected from the UL File" - Rains refers to the expert disclosure of John Datovech, the Defendant's engineering expert, in which he notes that UL independently determined the design and manufacturing of the Type 17 toaster complied with ANSI/UL 1026. "This means that the design of the McNeil toaster successfully passed the full battery of the required third-party evaluations and tests required by this standard."

The Defendant is permitted to introduce evidence of compliance with industry standards as evidence that the product was not negligently designed or manufactured (just as non-compliance would be admissible to prove the converse).

The substance of Rains' "commentary" and disclosed expert testimony is that the UL standard was revised subsequent to the time period during which the subject toaster was manufactured and sold to the plaintiff and that the subject toaster would not have met the revised standard.

Rains only identifies the date of revision as "circa 2001" rather than state the specific effective date of the revision, November 2001, which is included in the standard. One can only surmise that he failed to note the specific date because it was three months after the August 2001 fire which is the subject of this suit. Further, the revision was prospective and only required toasters manufactured after November 2001 to comply with the new standard. Further, the revision did not require any actions with regard to toasters that were manufactured prior to the effective date.

Further, Rains reportedly intends to comment on the fact that the revision was adopted "at the urging of the CPSC" (Consumer Products Safety Commission). As an initial matter, there is no admissible evidence regarding the role of the CPSC so the Court is unable to evaluate the significance of its "involvement." There is no probative value to the "evidence" that the CPSC urged a revision - without any finding the prior toaster design was faulty or dangerous, and in a way related to the facts of this case. On the other hand, reference to the CPSC would be unduly prejudicial to the Defendant as there may be a misperception or speculation that the CPSC made some specific findings with regard to the subject toaster.

Wherefore, the Defendant moves for an Order in Limine precluding reference to the revised UL standard or the CPSC.

The Defendant,

By its Attorneys,

Scott J. Tucker - BBO#503940

Tucker, Heifetz & Saltzman, LLP

100 Franklin Street

Boston, Massachusetts 02110

(617) 557-9696

Thereby certify that I made service of the foregoing document in accordance with the provisions of Fed. R. Civ. P. 5.

EXHIBIT "A"

UNITED STATES DISTRICT COURT FOR THE DISTRICT OF MASSACHUSETTS

VERMONT MUTUAL INSURANCE)	
COMPANY, as Subrogee of)	
Robert and Nancy McNeil, and)	
ROBERT and NANCY MCNEIL)	
Plaintiffs,)	
)	
V,)	C. A. NO. 04 CV 12257 NG
)	
HAMILTON BEACH PROCTOR-)	
SILEX, INC.,)	
Defendant.)	

PLAINTIFFS', VERMONT MUTUAL INSURANCE COMPANY, AS SUBROGEE OF ROBERT AND NANCY MCNEIL AND ROBERT AND NANCY MCNEIL, SUPPLEMENTAL EXPERT DISCLOSURES

Pursuant to Fed. R. Civ. P. 26(a)(2) and the Scheduling Order entered in this matter,
Plaintiffs' Vermont Mutual Insurance Company as Subrogee of Robert and Nancy McNeil and
Robert and Nancy McNeil ("Plaintiffs") supplements the following information regarding the
expert witnesses the Plaintiffs intend to call at the trial of this matter:

1. Michael J. Rains, P.E.
Engineering and Fire Investigations
634 State Road, Suite K
N. Dartmouth, MA 02747

Case 1:04-cv-12257 NG Document 20 Filed 99514/2006 Page 5 of 7

A. <u>Written Report</u> - Plaintiffs in addition to relying upon Mr. Rains' EFI, Engineering and Fire Investigations written report dated August 16, 2002, the Plaintiff's also rely upon Mr. Rains' August 21, 2006, written report which is appended hereto.

Plaintiffs, VERMONT MUTUAL INSURANCE COMPANY, ROBERT MCNEIL & NANCY MCNEIL By their attorneys,

S/ Douglas F. Hartman

R. Bart Warner
BBO# 552952
Douglas F. Hartman
BBO # 642823
MONAHAN & ASSOCIATES, P.C.
113 Union Wharf
Boston, MA 02109
(617) 227-1500

CERTIFICATE OF SERVICE

I, Douglas F. Hartman, hereby certify that on this 1st day of September, 2006, a copy of the forgoing was served upon all counsel of record by electronic filing through the United States District Court for the District of Massachusetts, ECF filing system.

S/Douglas F. Hartman

Douglas F. Hartman

9mcneil/suppexpdisclosure-rains



21 Father DeValles Bivd., Bldg. B Fall River, MA 02723 Tf: 800-326-5811 Tel: 508-997-4900 Fax: 508-991-8824

www.efiglobal.com

Comments on Report of John J. Datovech, P.E., C.F.E.I. re. C.A. No. 04CV12257NG dated April 17, 2006

- 1. Matters not in dispute There is no disagreement that:
 - The cause of the fire was the ignition of a "Kellogg's strawberry frosted pop tart" in a Hamilton Beach Proctor -Silex Model 22430, Type 17, electric toaster.
 - The toast timer control was on its highest setting (i.e.,"6").
 - There were no signs of abnormal electrical activity in the toaster wiring or the branch circuit wiring/receptacle powering the toaster.
 - The toaster latch striker was not engaging the slot in the latch. The timer and latch release mechanism likely operated properly.
- 2. Data Collected from the UL File Mr. Datovech states, "A review of UL File E6132, Vols. 1, 20, Sec. 19 indicates that UL independently determined the design and manufacturing of the Type 17 toaster complied with ANSI/UL 1026. This means that the design of the McNeil toaster successfully passed the full battery of the required third-party evaluations and tests required by this standard."
- My Comment UL would be the first to state that successfully meeting all requirements of its standard does not assure that a product cannot fail in an unsafe manner due to a design or manufacturing defect. Ironically, the standard cited, UL 1026, was revised circa 2001, at the urging of the CPSC, to upgrade the requirements for electric toasters. The McNeil toaster design does not meet the revised standard that requires that the heating elements be deenergized separately from movement of the food carriage. The design used in the McNeil toaster could not achieve UL listing under the current UL 1026 requirements as its deenergization requires the upward movement of the food carriage to operate the switch that supplies power to the heating elements.
- 3. The Equations Relating to Spring Force The equations are valid but their application in this situation is not valid. The problem is that the equations apply to an ideal spring used within its elastic limit. The spring in this toaster stretched well beyond its elastic limit and permanently deformed. Mr. Datovech's own photos show this deformation and he state's that in his experiment "the six active coils were permanently stretched a distance of 1.44 inch." This obviously changes the overall length of the spring and the distance to which it is stretched by the toaster carriage mechanism.

4. The Cause of the Lifter Spring Stretching Damage - This is the key difference in our opinions. Mr. Datovech opines that the stretching damage was a result of the heat of the fire and that this type of stretching is typical of toaster springs that have been in a fire. I agree that there is enough heat to cause toaster springs to stretch during a fire. Where I disagree is that springs that stretch solely due to the heat of a fire do not display an abrupt transition between no stretching and extreme stretching in the space of one coil as this spring did. It also displayed this abrupt transition precisely at the point where I believe it caught in the adjacent slot in the carriage mechanism.

5. Mr. Datovech's Experiment - Mr. Datovech's experiment had several flaws:

- It was not the same model toaster. I assume he could not obtain an identical toaster as it is out of production. Granted, the toaster used the same return spring but the carriage mechanism and switch were not identical to that of the McNeil toaster.
- He ran the experiment once. The McNeil toaster spring may have been subjected to thousands of operations prior to the fire.
- Most important ... why didn't he run an experiment using a pop tart to see if the pop tart would ignite with the toast dial at its highest setting? Kellogg pop tarts are readily available. Ignition of the pop tart would have supported his conclusion that this was what caused the pop tart to ignite.

6. My Experiment -

I ran the experiment that Mr. Datovech did not. As I could not obtain an identical toaster to the McNeil model, I used a Proctor-Silex Model 22427, Type 25 toaster. This toaster is functionally similar ... it is a two slot toaster with a toast dial calibrated from 1 (lightest) to 6 (darkest) and is rated 930-watts. I purchased a package of Kellogg strawberry frosted pop tarts at a local market. I placed two tarts in the toaster (facing in different directions to obtain worst-case w/r frosted side facing heating elements) and set the dial at its maximum setting of "6". At the end of the toast cycle (approximately 150-seconds), the tarts popped up with no sign of smoking or burning. I then initiated another cycle (after a delay of approximately one minute). Approximately one minute into this second cycle there was light smoking of the tarts visible. By the end of the cycle, the smoke had increased moderately but there was no flaming or other sign of ignition of the tarts or their frosted coatings. This experiment demonstrated that, even with the dial at its highest setting of "6", the pop tarts would not ignite in one or even two toast cycles. The results of this experiment contradict Mr. Datovech's conclusion that the cause of the fire was Mr. Doyle's misuse of the toaster in placing the toast control dial on its highest setting.